



D:\14086_Bistand_detailregulering_Moster-toppen\4-Prod\FB9\43-Teg\Lay_T.dwg

TEGNFORKLARING

BESKRIVELSE HELNING

- ∞ - 1:1,5
- 1:1,5 - 1:2
- 1:2 - 1:3
- 1:3 - 1:4
- 1:4 - 1:6
- 1:6 - 0

<small>Rev.</small>	<small>Endring/ erstatning</small>	<small>Tegn.</small>	<small>Kontr.</small>	<small>Dato</small>
Kringelåslia AS				
Reguleringsplan 201710				
Kringelåslia nedre				
Helningskart				
<small>Tegn.</small>	<small>Kontr.</small>	<small>Ansv.</small>		
ASV	TCH	TCH		
<small>Dato:</small>		2018.08.06		
<small>Oppdragsnr.:</small>		17066		
<small>Kart og høydereferanse:</small>				
NN2000				
<small>Målestokk:</small>				
Horisontal: 1:1000 (A1)				
<small>Vertikal:</small>				
T01				



Structor Lillehammer
 AS Fåberggata 116
 2615 Lillehammer
 lillehammer@structor.no